
## **Stainless Steel Ball Valve**



# 2 Piece • Standard Port • Threaded Connection • 2000 WOG • with Spring Return Handle



T-SS-2000N-DH




- 1-1/4" 2" 3 piece, 4 bolt pattern
- Fail safe position
- Solid ball construction
- 29 in-Hg vacuum rating
- 100% leak tested
- Wetted surfaces contain less than .25% lead content


### Approvals USTED

- UL Listed (1/4" 2")
  - MHKZ Manual valves
  - YQNZ Compressed gas shut-off valves
  - YRBX Flammable liquid shut-off valves
  - YRPV Gas shut-off valves
  - YSDT LP gas shut-off valves
  - YQAR Anhydrous ammonia shut-off valves
- MSS SP-110
- ANSI B1.20.1

#### **Valve Seat Rating**

1/4 - 1" 2000 WOG - 150 WSP, 1-1/4" - 2" 1000 WOG - 150 WSP





#### **Material Specifications**

No.	Part	Materials					
1	Body	CF8M Stainless Steel					
2	End Connection	CF8M Stainless Steel					
3	Ball	CF8M Stainless Steel					
4	Seat (2)	Hostaflon® TFM 1600					
5	Stem	316 Stainless Steel					
6	Packing (2)	RPTFE					
7	Stem Seal	Hostaflon® TFM 1600					
8	Packing Gland	316 Stainless Steel					
9	Body Seal	Hostaflon® TFM 1600					
10	Handle - Dead Man	304 / 301 Stainless Steel					
11	Handle Nut	304 Stainless Steel					
12	Lock Washer	304 Stainless Steel					

Note: For 1-1/4" - 2" material specifications see A1000

#### **Dimensions**

Part No.	Size	Α	В	С	D
100-931DH	1/4"	2.07	1.76	7.09	0.37
100-932DH	3/8"	2.07	1.76	7.09	0.37
100-933DH	1/2"	2.34	1.92	7.09	0.50
100-934DH	3/4"	2.80	2.40	7.28	0.69
100-935DH	1"	3.23	2.56	7.28	0.87
100-936DH*	1-1/4"	4.33	2.71	8.66	1.38
100-937DH*	1-1/2"	4.75	3.22	11.02	1.63
100-938DH*	2"	5.52	3.55	11.02	1.97

\*1-1/4" - 2" 3 piece, 4 bolt pattern

To loosen the spring tension, you have to unscrew the handle cover. Under the cover, there is a threaded rod with a long spring over it with a nut on the end. Loosen the nut to decrease the spring force. Be careful not to loosen too much, then the valve will not fully close.



**WARNING:** This product can expose you to chemicals including diisononyl phthalate (DINP), which is known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.